SPARE PARTS & COMPLETE UNITS

MORRIS
10 H.P. SERIES M

DESCRIPTION OF PART.	QUOTE THIS PART NO.	ENGLISH LIST PRICE. £ s. d.	
DYNAMO—C45YV-3 TYPE L ...	228,139	4 15 0	ea.
Field Coils	228,075	7 9	set
Term. Block cover c/w fxg. screw ...	238,234	9	ea.
Band cover assembly	227,015	1 0	ea.
D.E. Bracket assembly—less bearing...	237,119	9 0	ea.
D.E. Bearing	189,308	8 3	ea.
Armature (wound)	228,061	*	
C.E. Bracket c/w bush and brushgear less brushes	228,143	14 0	ea.
C.E. Bearing bush	L4032/1	9	ea.
Brush set	203,148	2 9	set
Brush spring set	228,159	8	set
STARTER—M418G TYPE L ...	255,378	4 15 0	ea.
Field Coils set	255,625	8 9	set
Band cover c/w nut and screw ...	255,054	1 9	ea.
C.E. Bracket c/w brushgear and brg. bush—less brushes	255,478	11 0	ea.
C.E. Bearing bush	255,491	6	ea.
Brush set	255,659	2 0	set
Brush spring set	270,004	9	set
D.E. Bracket c/w bush	255,073	7 9	ea.
D.E. Bracket bush	270,038	1 3	ea.
Armature	255,463	*	
Pinion and sleeve assembly	255,649	14 0	ea.
Main spring	L3297/3	1 9	ea.
Spring (pinion retaining)	255,728	6	ea.
Shaft nut	L1988/5	1 3	ea.
STARTER SWITCH—ST18 TYPE L5	764,248	5 6	ea.
Knob	764,354	6	ea.
Spring	764,059	3 0	doz.†
Rubber grommet	729,423	6	ea.
DISTRIBUTOR—DK4A TYPE A109	405,569/S	1 19 9	ea.
Lubricator	405,979	9	ea.
Shaft and action plate	400,116	4 9	ea.
Cam	406,329	4 9	ea.
Auto advance weight	400,147	1 3	ea.
Auto advance toggle	400,141	6	ea.
Auto advance springs (set)	M3839/4/S	6	set
Contact set	400,415	3 6	set
Condenser assembly	400,308	2 6	ea.
Distributor arm assembly (or rotor)...	400,051	1 3	ea.
Distributor cover ass. c/w cable nuts	400,135	3 9	ea.
Nut (moulded)—distributor	M3156/4	4 6	doz.†
Distributor carbon & spring assembly	404,435	6	ea.
Securing plate assembly	404,422	1 6	ea.
Screwdriver & point gauge assembly...	400,174	6	ea.
COIL—Q12/8	401,650	15 0	ea.
Coil fixing clip	I.C.C.	1 6	ea.
CONNECTOR BOX—4J	770,069	2 0	ea.
Cover and screw assembly	770,058	9	ea.
‖JUNCTION BOX—RF91 TYPE L4	334,573	1 19 9	ea.
Fuse assembly (25-amp.)	FA25	1 6	box
Fuse cover	334,553	2 6	ea.
Fuse cover spring clip	334,561	2 9	doz.†
Resistance (63 ohms)	337,906	1 6	ea.
Regulator	390,674	1 2 3	ea.
PANEL PARTS—			
AMMETER—CZ20 TYPE L22 ...	364,536	6 0	ea.
Bulb (panel light)	1224M	1 0	ea.
Bulb (warning light)	C252A	3	ea.
PANEL SWITCH—PS6 TYPE L17 ...	314,146	3 0	ea.
SWITCHBOX—PLC2 TYPE L43 ...	344,472	10 6	ea.
WARNING LIGHT—WL3 TYPE L...	318,522	3 9	ea.
Warning light rim and glass	LR41	1 0	ea.
‡HEADLAMP—MD140EDS PRIMER/CPR.	509,981	3 2 6	ea.
‡HEADLAMP—MD140 PRIMER/CPR.	509,982	1 17 6	ea.
Fixing screw	505,122	1 0	ea.
Rim catch assembly	509,936	1 0	ea.
Reflector c/w thrust plate, b/holder, swivel ass., joint and tension spg.	508,247	9 3	ea.

DESCRIPTION OF PART.	QUOTE THIS PART NO.	ENGLISH LIST PRICE. £ s. d.	
HEADLAMPS—Continued—			
Reflector c/w b/holder (non-dip type)	506,854	9 3	ea.
Extension rim assembly	508,248	6 9	ea.
Dipper unit c/w fixings	501,014	9 9	ea.
Dipper unit fuse	FA6	1 6	box
Bulb holder complete	504,804	1 6	ea.
Bulb holder clip and screw	N890	4 6	doz.†
Front rim ass. c/w joint bead & glass wires	506,861	6 6	ea.
Glass only	NC869/3	2 6	ea.
Bulb	54	2 1	ea.
‡HEADLAMP—MD140ED VERTICAL PRIMER/CPR. (EXPORT) ...	506,957	3 2 6	ea.
‡SIDELAMP—LD109 PRIMER/CPR ...	524,629	6 6	ea.
Base	524,054	4 6	doz.†
Reflector c/w joint bead and fixing wires	521,990	1 3	ea.
Bulb holder c/w interior	520,340	6	ea.
Front Rim assembly—less glass ...	521,989	1 3	ea.
Front Rim fxg. screw & locking plate	523,429	2 3	doz.†
Glass only	520,336	6	ea.
Bulb	207	1 0	ea.
STOP TAIL LAMP—ST50 TYPE L	523,752	12 6	ea.
Back plate assembly	523,800	4 6	ea.
Clasp assembly	522,265	3 6	doz.†
Glass	522,264	1 0	ea.
Bulb	207	1 0	ea.
BRAKE PEDAL SWITCH—55C ...	315,739	2 9	ea.
‖HORN—HF935	Use Movement		
Horn movement	700,339	2 3 0	ea.
Bracket and fixing screw	700,301	2 6	ea.
‖WINDSCREEN WIPER—SW4 TYPE A109	734,456	Use Motor Unit	
Motor unit	734,357	1 18 3	ea.
Brushgear c/w brushes	733,661	4 0	ea.
Brushes (set)	729,367	9	set
Clutch housing and switch assembly...	734,408	3 0	ea.
Spindle assembly (drivers side) ...	734,467	2 3	ea.
Spindle assembly (pilot side) ...	734,468	2 3	ea.
Knob c/w set screw (drivers side)...	729,374	1 0	ea.
Knob c/w set screw (pilot side) ...	729,373	1 0	ea.
Arm assembly	727,946	3 6	ea.
Squeegee assembly	727,802	1 6	ea.
MIRROR—542/43	580,574	6 0	ea.
Mirror	580,603	2 6	ea.
Mirror bracket assembly	580,891	4 6	ea.
Fixing clip assembly	580,575	3 3	doz.†
‖TRAFFICATOR—SF40F/24G ...	Use Movement only		
Trafficator movement	539,323	17 9	ea.
Arm c/w top cover and bulb lead ...	538,277	5 9	ea.
Bulb	256	1 6	ea.
BATTERY—less COVER & FITTINGS	STXW9A/ Dry	4 19 0	ea.
Terminal lug complete—pos.	S2267/1/L	2 3	ea.
Terminal lug complete—neg.	S2267/2	9	ea.
Vent plug c/w washer	S2106/4	5 6	doz.†
DIPPER SWITCH—FS22/1 ...	360,007	3 6	ea.
‖LUVAX SHOCK ABSORBERS—			
S.A. Movement c/w Lever Arm—Front Nearside	P5/4/ S5333	1 7 6	ea.§
S.A. Movement c/w Lever Arm—Front Offside	P5/3/ S5333	1 7 6	ea.§
S.A. Movement c/w Lever Arm—Rear Nearside	P4/3/ S5334	1 0 0	ea.§
S.A. Movement c/w Lever Arm—Rear Offside	P4/4/ S5334	1 0 0	ea.§
Filler Plug	9038/12	2 0	doz.†
Luvax Fluid (pint tin)	LM62	1 9	tin
Luvax Pressure Oiler	780,102	10 6	ea.

§Return for repair.

* For Armature Prices Refer to our Armature Exchange Service. † Each Price 6d. † ‡Supplied in various Finishes—state Finish required.
‖ These items subject to special exchange price.

JOSEPH LUCAS LTD.
PHONE: SERVICE PARTS & REPAIRS—CEN 8401

BIRMINGHAM 19, ENGLAND
TELEGRAMS: "LUCAS BIRMINGHAM."

SPECIFICATION OF EQUIPMENT.

MORRIS IO-HP. CAR, SERIES "M".

UNIT.	TYPE.	SERVICE REF.NO.
DYNAMO.	C45YV/3. L/I.	228I39.
STARTER.	M4I8 G.L.	255378.
STARTER SWITCH.	STI8 L5.	764248.
BATTERY.	BNW9A.	
CONTROL BOX.	RF9I. L4.	334573.
DISTRIBUTOR.	DK4A. AI09.	405569.
IGNITION COIL.	QI2 - L.	40I650.
SWITCHBOX.	PLC2. L43.	344472.
DIP SWITCH.	FS22/I.	360007.
TRAFFICATORS.	SF40F/90°24G.	539323.(MOVEMENT.)
WINDSCREENWIPERS.	SW4. AI09.	734456. 734357. MOTOR.
HORN.	HF935.	700379.
CONTROLS. S/COL.	A/IO/39.	323470.
MIXTURE.	A/IOC/39.	328855.
MIRROR.	542/43.	580574.
HEADLAMPS.	MDI40.	MAROON. LH. 506933. RH. 506934. DARK BLUE: LH. 506935. RH. 506936. LIGHT BLUE: LH. 506937. RH. 506938.

Cont'd.

MORRIS IO-HP. CAR, SERIES "M".

UNIT.	TYPE.		SERVICE REF.NO.
HEADLAMPS. (Cont'd.)	MDI40.	GREEN. LH.	506939.
		RH.	506940.
		BLACK. LH.	50694I.
		RH.	506942.
		BROWN. LH.	509989.
		RH.	50990.
SIDELAMPS.	LDI09/I.	MAROON.	524623.
		DARK BLUE.	524624.
		LIGHT.	524625.
		GREEN.	524626.
		BLACK.	524628.
		PRIMER.	524629.
		BROWN.	52463I.
STOP TAIL LAMP.	ST50B.		523752.
CABLES.			963060E-07IA.
SHOCK ABSORBERS. LUVAX PISTON TYPE.	FRONT LH.		P5-4-53-33X.
	RH.		P5-3-53-33Y.
	REAR LH.		P4-3-53-34Y.
	RH.		P4-4-53-34X.

THIS CANCELS ADVANCE SPECIFICATION.