



SPARE PARTS & COMPLETE UNITS

MORRIS

"EIGHT" MODEL SERIES II

DESCRIPTION OF PART.	QUOTE THIS PART NO.	ENGLISH LIST PRICE.	DESCRIPTION OF PART.	QUOTE THIS PART NO.	ENGLISH LIST PRICE.
DYNAMO—C45N/3 A86/0		£ s. d.			£ s. d.
6v. CLOCK	228,183	4 12 6 ea.	PANEL—C/A337/1	303,547	
Field Coils Set	228,068	7 9 set	Ammeter	364,387	6 0 ea.
Terminal Block Cover c/w Fxg. Screw	238,234	9 ea.	Bulb—Panel Light	200	1 3 ea.
Band Cover Assembly	227,015	1 0 ea.	Bulb—Warning Light	C252A	3 ea.
D.E. Bracket Ass. less Bearing	228,171	2 9 ea.	Panel Connectors c/w Bulb Holders	999,063	1 3 ea.
D.E. Ballrace	189,308	8 3 ea.	Switchbox c/w Fixing Spring	344,501	9 6 ea.
Oiler—screw-in-type c/w Spring Ball (C.E. Bracket)	238,370	8 ea.	Ass. Base c/w Rivetted Terminals	344,192	3 3 ea.
Wick and Spring Assembly (screw-in-type Oiler)	L4034/1	3 3 doz.	Cover	L3784/1	1 6 ea.
Armature	228,067		Handle c/w Fixing Washer	344,227	2 0 ea.
C.E. Bracket c/w Main Brushgear Ass. less Brushes and Bearing Bush	228,143	14 0 ea.	Ignition Stem Assembly	L3972/4	4 6 doz.†
Brush Set	228,179	3 3 set	Ignition Key	L4449/3	6 ea.
Brush Spring Set	228,159	8 set	Ignition Contact Plate c/w Contacts	L4370/1	3 6 doz.†
Through Fixing Bolt	228,066	6 ea.	Rotor Insul Plate—thin	344,282	2 3 doz.†
STARTER—M35G L2/0			Rotor Ass.	344,071	1 6 ea.
6v. CLOCK INBOARD	250,405	4 6 0 ea.	Switch Spring	L4542/1	3 0 doz.†
Field Coils Set	250,462	6 3 set	Fixing Spring c/w Screw and Nut	344,197	9 ea.
Band Cover Assembly	250,322	1 3 ea.	Warning Light	318,504	3 9 ea.
C.E. Bracket Ass. c/w Switch Contact details and soldered on Brush	250,291	8 6 ea.	Rim and Glass Assembly	LR41/CP	1 0 ea.
C.E. Bracket Bearing Bush	L2101/1	9 ea.			
Brushes—pair	255,659	2 0 pr.	PANEL—C/A3838		
Brush Spring Set	270,004	9 set	(OVERSEAS—AUSTRALIA)	304,043	
Contact Details Set (located on C.E. Bracket)	255,637	3 ea.	Switchbox PLC2 L	344,078	10 6 ea.
Through Fixing Bolt	228,066	6 ea.	Base Assembly	344,082	3 6 ea.
D.E. Bracket c/w Bearing Bush	250,412	4 0 ea.	Handle c/w Fixing Screw	344,094	1 3 ea.
D.E. Bracket Bearing Bush	L3522/2	9 ea.	Ignition Rotor Assembly	344,080	3 0 doz.†
Armature	250,414		Otherwise as C/A337/1.		
Pinion and Sleeve Ass. c/w Retaining Spring, Guide and Washer	250,415	14 0 ea.	HEADLAMP—L131 BLACK	505,063	1 2 0 ea.
Main Spring	250,404	9 ea.	HEADLAMP—L131EDS BLACK 6v.	505,062	1 19 6 ea.
Pinion Retaining Spring	250,095	1 9 doz.†	Reflector Ass. c/w Bulb Holder L131	505,111	7 3 ea.
Nut or Main Spring Cup (Shaft D.E.)	L1178/4	1 0 ea.	Reflector Ass. c/w Bulb Holder, Thrust Plate, Tension Spring, Swivel Ass. & Joint Bead L131EDS	501,308	8 3 ea.
STARTER SWITCH	764,251	3 9 ea.	Action Bracket & Location Shell Ass.	500,163	4 0 ea.
DISTRIBUTOR—DK4A/0 A53			Dipper Unit c/w Screws & Washers	501,013	9 9 ea.
CLOCK	404,288	1 19 9 ea.	Dipper Unit Fuse (box of 6)	FA10	1 6 box
Distributor Cover Securing Clip	M2375/2	3 3 doz.†	Set of Dipper Swivel Parts	500,160	9 set
Lubricator	400,304	8 ea.	Bulb Holder Assembly L131	500,061	9 ea.
C.B. Lever Ass. c/w Angle Ass. and Fixing Parts	400,415	3 6 ea.	Set of Bulb Holder Interior Components	500,181	6 set
Condenser c/w Clip and Fixing Parts	400,308	2 6 ea.	Front Rim Ass. less Glass	505,620	4 6 ea.
Distributor Arm Assembly	400,051	1 3 ea.	Glass	MW534	1 6 ea.
Distributor Cover c/w Cable Nuts	400,135	3 9 ea.	Bulb	106	2 3 ea.
Distributor Carbon and Spring	404,435	6 ea.	HEADLAMP—L131ED	505,646	1 19 6 ea.
Distributor Cover Cable Nuts	M3156/4	4 6 doz.†	Otherwise as above.		
Securing Plate Ass.	400,367	1 3 ea.	HEADLAMP—LG131 (OVERSEAS)	505,908	1 6 0 ea.
Driving Dog	M1106/4	1 0 ea.	Fixing Screw	500,143	4 6 doz.
Screwdriver and Gauge Assn.	400,174	6 ea.	Fixing Screw Nut	180,338	1 9 doz.
Shaft and Action Plate	400,116	4 6 ea.	Reflector c/w Bulb Holder	505,865	8 0 ea.
Auto Advance Weight	400,147	1 3 ea.	Front Rim Ass. c/w Joint Bead and Glass Wires	505,620	4 6 ea.
Auto Advance Spring	M3839/3	6 pr.	Glass only	NC316/7	2 0 ea.
Auto Advance Spring	M3847/2	6 pr.	Bulb	102	3 6 ea.
Auto Advance Toggle	400,141	6 ea.	Otherwise as L131EDS.		
Shaft Bearing Bush (5/8in. long)	404,374	6 ea.	HEADLAMP—L131FT (OVERSEAS		
Shaft Bearing Bush (13/16in. long)	M3192/3	6 ea.	—DENMARK)	506,625	1 12 6 ea.
Cam	400,046	4 9 ea.	Reflector Ass. c/w Bulb Holder	532,588	14 0 ea.
IGNITION COIL—6Q6	401,648	15 0 ea.	Bulb Holder Ass.	532,637	2 0 ea.
Bracket Fixing Clip	1CC	1 9 ea.	Reflector Back Shell Ass.	532,598	2 3 ea.
CUT-OUT AND JUNCTION BOX			Front Rim Assembly	505,620	4 6 ea.
CFR2 L4	332,179	16 0 ea.	Glass (special fluted)	504,108	2 0 ea.
Cut-out	339,203	7 0 ea.	Otherwise as LG131.		
Cut-out Cover	332,153	1 9 ea.	SIDELAMP—LD105 6v. BLACK	522,203	5 3 ea.
Fuse Ass. (25 amp.)	FA25	1 6 box	Base	521,204	3 0 doz.†
Fuse Ass. (6 amp.)	FA6	1 6 box	Fixing Screw Assembly	520,342	8 ea.
Resistance	332,178	6 ea.	Fixing Screw	520,325	4 6 doz.†
			Fixing Screw Nut	181,260	2 0 doz.†

†For Armature Prices refer to Armature Exchange Service.†

JOSEPH LUCAS LTD.
PHONE: SERVICE PARTS & REPAIRS—CEN. 8401BIRMINGHAM 19, ENGLAND
TELEGRAMS: "LUCAS. BIRMINGHAM."



SPARE PARTS & COMPLETE UNITS

DESCRIPTION OF PART.	QUOTE THIS PART NO.	ENGLISH LIST PRICE.	DESCRIPTION OF PART.	QUOTE THIS PART NO.	ENGLISH LIST PRICE.
SIDELAMP—Contd.—		£ s. d.	SCREENWIPER—Contd—		£ s. d.
Reflector c/w Joint Bead and Fixing Wires	521,990	1 3 ea.	Brush Springs (set)	730,387	2 0 doz.†
Bulb Holder c/w Interior Components	520,340	6 ea.	Arm Assembly	727,973	3 6 ea.
Front Rim Ass. c/w Fixing Wires ...	522,221	9 ea.	Squeegee Assembly	727,802	1 6 ea.
Glass only	521,215	6 ea.	Otherwise as DW3 A53.		
Bulb	200	1 3 ea.			
STOP TAIL LAMP—ST38/AS/L2			MIRROR—564/36	580,823	5 0 ea.
6v. BLACK	520,428	12 6 ea.	Mirror	580,820	1 0 ea.
Contact Ass.	NC446/6A	2 3 ea.	Fixing Bracket and Plate Ass. ...	580,825	3 9 ea.
Front Rim Ass. less Glass (black) ...	520,445	1 3 ea.	Mirror Clip Plate	580,818	9 ea.
Glass	520,410	1 3 ea.			
Bulb—6v.	200	1 3 ea.	TRAFFICATOR—SF34F 6v.		
BRAKE PEDAL SWITCH—54C ...	315,725	2 6 ea.	SALOON	539,131	See Movement
Spring	315,714	2 3 doz.	TOURER	539,130	
HORN—HF935	701,147	See Movement	Trafficator Movement	539,112	16 9 ea.
Horn Movement	700,340	1 5 0 ea.	Arm c/w Top Cover and Bulb Lead		
Bracket Assembly	700,301	2 6 ea.	less Bulb	531,605	5 6 ea.
Bracket Fixing Screw	108,299	2 6 doz.†	Bulb	255	2 0 ea.
SCREENWIPER—DW3 A53 (Saloon)	731,051	See Replacement Unit	Fixing Plate No. 15G (Saloon) ...	538,316	9 ea.
Replacement Unit	731,064	1 5 0 ea.	Fixing Plate Screw	100,033	9 doz.†
Front Cover Ass. c/w Fixing Parts ...	730,926	2 0 ea.	Case Ass. (Tourer)	538,416	3 0 ea.
Brushgear Assembly	730,790	2 9 ea.	CONTROL ARM—CS58A/1 ...	310,239	14 9 ea.
Wound Coil and Pole Assembly ...	730,937	3 6 ea.	Clip Assembly	310,207	9 ea.
Armature Assembly	731,017	6 6 ea.	Horn Push and Dipper Switch ...	380,101	4 3 ea.
Lubricator and Wick Ass.	730,386	6 ea.	Trafficator Switch	310,396	3 0 ea.
Intermediate Gear and Pinion Ass. ...	730,787	1 6 ea.	BATTERY—LESS COVER AND		
Arm Ass. 5½" E.B.	732,116	3 6 ea.	FITTINGS	SLTW11E/	
Squeegee Assembly 8in. E.B.	727,802	1 6 ea.	Dry		2 9 6 ea.
SCREENWIPER —DW3 A66 ...	731,136	See Replacement Unit	Terminal Lug complete—pos. ...	S2267/1/L	2 3 ea.
(TOURER)			Terminal Lug complete—neg. ...	S2267/2	1 0 ea.
Replacement Unit	731,135	1 5 0 ea.	Vent Plug c/w Washer	S2106/4D	6 0 doz.†
Brushgear c/w Brushes	731,001	2 9 ea.	CABLE HARNESS		
Brushes (set)	730,388	1 0 set	MAIN (Home)	960,560	1 19 0 set
			CABLE HARNESS		
			STARTER (Home)	960,571	10 0 set
			CABLE HARNESS		
			MAIN (OVERSEAS)	960,580	2 2 0 set
			CABLE HARNESS		
			STARTER (OVERSEAS)	960,591	9 6 set

All Prices subject to alteration without notice. †—Each price 6d. †

JOSEPH LUCAS LTD.
PHONE: SERVICE PARTS & REPAIRS—GEN. 8401

BIRMINGHAM 19, ENGLAND
TELEGRAMS: "LUCAS. BIRMINGHAM."

