



## SPARE PARTS &amp; COMPLETE UNITS

MORRIS  
SERIES "E" 8 H.P. MODEL

DESCRIPTION OF PART.	QUOTE THIS PART NO.	ENGLISH LIST PRICE.	DESCRIPTION OF PART.	QUOTE THIS PART NO.	ENGLISH LIST PRICE.
		£ s. d.			£ s. d.
DYNAMO—C45YV/3 A108 6v.			HEADLAMPS—Contd.—		
CLOCK C.V.C. ... ..	228,269	4 10 0 ea.	Dipper Unit Fuse ... ..	FA10	1 6 box
Field Coils ... ..	228,228	7 9 set	Main Bulb Lead Assembly ... ..	509,741	6 ea.
Terminal Block Cover c/w Fxg. Screw	238,234	9 ea.	Pilot Bulb Lead Assembly ... ..	509,742	6 ea.
D.E. Bracket Assembly less Bearing	228,171	2 9 ea.	Front Rim Assembly c/w Joint Bead		
D.E. Bearing ... ..	189,308	8 3 ea.	and Glass Wires ... ..	509,744	7 6 ea.
*Armature ... ..	228,067		Glass only ... ..	523,722	2 6 ea.
C.E. Bracket c/w Bush and Brushgear			Bulb (Main) ... ..	72	2 1 ea.
less Brushes ... ..	228,143	14 0 ea.	Bulb (Pilot) ... ..	200	1 0 ea.
C.E. Bearing Bush ... ..	L4032/1	9 ea.	STOP TAIL LAMP—ST50B/EB 6v.	523,808	12 6 ea.
Brush Set ... ..	203,148	2 9 set	Back Plate Assembly ... ..	523,800	4 3 ea.
Brush Spring Set ... ..	228,159	8 set	Clasp Assembly ... ..	522,265	3 6 doz.†
STARTER—M35G/0 L2 6v. ... ..	250,405	4 6 0 ea.	Hinge Wire ... ..	521,545	1 0 doz.†
Field Coils Set ... ..	250,462	6 3 set	Glass ... ..	522,264	1 0 ea.
Band Cover c/w Nut and Screw ... ..	250,322	1 3 ea.	Bulb ... ..	200	1 0 ea.
C.E. Bracket Ass. c/w Sw. Contact			BRAKE PEDAL SWITCH—54C ... ..	315,725	2 6 ea.
Details and 2 soldered-on Brushes	250,291	8 6 ea.	Springs ... ..	315,714	2 3 doz.†
C.E. Bearing Bush ... ..	L2101/1	9 ea.	*HORN—HF935 ... ..	700,315	Use Movement
Brushes—pair ... ..	255,659	2 0 set	Horn Movement (HF934) ... ..		2 2 6 ea.
Brush Spring Set ... ..	270,004	9 set	Bracket and Fixing Screw Assembly ... ..	700,301	2 6 ea.
D.E. Bracket c/w Bush ... ..	250,412	4 0 ea.	Bracket Fixing Screw ... ..	108,278	2 6 doz.†
D.E. Bracket Bush ... ..	L3522/2	9 ea.	*WINDSCREEN WIPER—SW4 A110		
*Armature ... ..	250,414		(R.H.D.) 6v. SINGLE ARM ... ..	734,645	Use Motor Unit
Pinion and Sleeve Assembly ... ..	250,415	14 0 ea.	Motor Unit ... ..	734,523	1 18 3 ea.
Main Spring ... ..	250,404	9 ea.	End Cover Moulding c/w Terminal Cap	733,913	3 9 ea.
STARTER SWITCH—ST10 L ... ..	764,251	3 9 ea.	Brushgear c/w Brushes ... ..	733,661	4 0 ea.
DISTRIBUTOR—DK4A A110 ... ..	405,568	See Service Unit	Clutch Housing Switch Assembly ... ..	734,408	3 0 ea.
Service Unit ... ..	405,568/S	1 19 9 ea.	Spindle Assembly ... ..	734,467	
Shaft Bearing Bush ... ..	404,374	6 ea.	Knob c/w Set Screw (driver's side) ... ..	729,374	1 0 ea.
Shaft Bearing Bush ... ..	M3192/3	6 ea.	Arm Assembly ... ..	727,946	3 6 ea.
Lubricator ... ..	405,979	9 ea.	Squeegee Assembly ... ..	727,802	1 6 ea.
Shaft and Action Plate (7°-9°) ... ..	400,114	4 9 ea.	*WINDSCREEN WIPER—SW4 A112		
Cam ... ..	406,329	4 9 ea.	(L.H.D.) 6v. SINGLE ARM ... ..	734,646	Use Motor Unit
Auto Advance Springs ... ..	M3844/1/S	6 set	For Spares see above.		
Contact Set ... ..	400,415	3 6 set	MIRROR—542/43 ... ..	580,574	6 0 ea.
Condenser Assembly ... ..	400,308	2 6 ea.	Mirror only ... ..	580,603	2 6 ea.
Distributor Arm Assembly (or Rotor)	400,051	1 3 ea.	Mirror Bracket Assembly ... ..	580,891	4 6 ea.
Distributor Cover Ass. c/w Cable Nuts	400,135	3 9 ea.	*TRAFFICATOR—SF40/F90° 24G		
Distributor Carbon and Spring Ass. ... ..	404,435	6 ea.	6v. ... ..		Use Movement
Securing Plate Assembly ... ..	400,367	1 3 ea.	Trafficator Movement ... ..	539,322	17 9 ea.
Screwdriver and Point Gauge Ass. ... ..	400,174	6 ea.	Arm c/w Top Cover and Bulb Lead ... ..	538,277	5 9 ea.
COIL—6Q6/8 L ... ..	401,648	15 0 ea.	Fixing Bracket ... ..	538,258	9 ea.
Coil Fixing Clip ... ..	1CC	1 6 ea.	Bulb ... ..	255	1 6 ea.
*JUNCTION BOX—RF91 L1 ... ..	334,551	1 19 9 ea.	BATTERY—LESS COVER AND		
Fuse Assembly (25-amp.) ... ..	FA25	1 6 box	FITTINGS STXW9E ... ..	STXW9E	/Dry 2 7 6 ea.
Resistance (field) 63-ohms. ... ..	337,906	1 6 ea.	Terminal Lug complete—pos. ... ..	S2267/1/L	2 3 ea.
Regulator ... ..	390,668	1 2 3 ea.	Terminal Lug complete—neg. ... ..	S2267/2	1 0 ea.
Regulator Cover ... ..	334,553	2 6 ea.	Vent Plug c/w Washer ... ..	S2106/4D	6 0 doz.
Regulator Cover Spring Clip ... ..	334,561	2 9 doz.†	DIPPER SWITCH—FS22/1 L6 ... ..	360,013	3 6 ea.
HEADLAMP—FF133/AP EDS 6v. ... ..	509,702	2 5 0 ea.	PANEL PARTS		
HEADLAMP—FF133/AP 6v. ... ..	509,718	1 12 6 ea.	Switchbox PLC2 L47 ... ..	344,484	10 6 ea.
Reflector c/w Thrust Plate, Bulb			Bulb—Panel Light ... ..	200	1 0 ea.
Holder, Swivel Assembly, Joint and			Bulb—Warning Light ... ..	C252A	3 ea.
Tension Spring ... ..	509,745	8 6 ea.	Panel Switch PS6 L17 ... ..	314,146	3 0 ea.
Reflector c/w Bulb Holder (non-dip			Warning Light WL3 L ... ..	318,504	3 9 ea.
type) ... ..	509,746	7 6 ea.	Warning Light Rim and Glass ... ..	LR41/CP	1 0 ea.
Action Bracket Assembly ... ..	509,739	4 0 ea.			
Dipper Unit c/w Fixing Screws ... ..	509,743	9 9 ea.			

\* These items are subject to special exchange prices.

†—Each price 6d.† All Prices in this list subject to alteration without notice.

JOSEPH LUCAS LTD.  
PHONE: SERVICE PARTS & REPAIRS—CEN. 8401BIRMINGHAM 19, ENGLAND  
TELEGRAMS: "LUCAS. BIRMINGHAM."