



## SPARE PARTS &amp; COMPLETE UNITS

MORRIS  
"EIGHT" MODEL SERIES I

DESCRIPTION OF PART.	QUOTE THIS PART NO.	ENGLISH LIST PRICE.	DESCRIPTION OF PART.	QUOTE THIS PART NO.	ENGLISH LIST PRICE.
<b>STARTER—M35A/0 A86/1</b>		£ s. d.	<b>DISTRIBUTOR—Contd.—</b>		£ s. d.
6v. CLOCK ... ..	250,372	4 5 0 ea.	Auto Advance Spring ... ..	M3839/3	} 6 pr.
Field Coils Set ... ..	250,035	10 0 set	Auto Advance Spring ... ..	M3847/2	
Band Cover c/w Nut and Screw	250,065	1 4 ea.	Auto Advance Toggle ... ..	400,141	
C.E. Bracket c/w Brushgear and Bearing Bush ... ..	250,163	6 0 ea.	Shaft Bearing Bush (5/16in. long) ...	404,374	
Brush Set ... ..	250,055	1 6 set	Shaft Bearing Bush (13/16in. long) ...	M3192/3	6 ea.
Brush Spring Set ... ..	250,056	8 set	Cam ... ..	400,046	4 6 ea.
Fixing Bolt ... ..	250,192	4 0 doz.†	<b>IGNITION COIL—6Q6</b> ... ..	401,648	15 0 ea.
D.E. Bracket c/w Bearing Bush ... ..	250,183	6 0 ea.	Bracket Fixing Clip ... ..	1CC	1 6 ea.
Armature ... ..	250,186	1 15 0 ea.	<b>CUT-OUT AND JUNCTION BOX</b>		
Pinion and Sleeve Ass. ... ..	250,116	12 6 ea.	—CFR2 L4 ... ..	332,179	15 0 ea.
Main Spring ... ..	L3352/1	1 6 ea.	Cut-out ... ..	339,203	6 6 ea.
<b>STARTER SWITCH—</b> ... ..	764,150	3 6 ea.	Cut-out Cover ... ..	332,153	1 6 ea.
<b>STARTER—M35G L2/0</b>			Fuse Ass. (25-amp.) ... ..	FA25	1 6 box
6v. CLOCK INBOARD ... ..	250,405		Fuse Ass. (6-amp.) ... ..	FA6	1 6 box
Field Coils Set ... ..	250,251		Resistance ... ..	332,178	6 ea.
Band Cover Ass. ... ..	250,322		<b>PANEL—C/A337</b> ... ..		
C.E. Bracket Ass. c/w Switch Contact Details and Soldered on Brush ...	250,291		Ammeter ... ..	364,008	5 0 ea.
C.E. Bracket Bearing Bush ... ..	L2101/1	1 0 ea.	Bulb—Panel Light ... ..	200	1 3 ea.
Brushes—pair ... ..	255,659	2 0 pr.	Bulb—Warning Light ... ..	C252AMES	3½ ea.
Brush Spring Set ... ..	270,004	9 set	Switchbox c/w Fixing Spring ... ..	344,159	8 6 ea.
Contact Details Set (located on C.E. Bracket) ... ..	255,657	1 0 ea.	Ass. Base c/w Rivetted Terminals	344,192	3 0 ea.
Through Fixing Bolt ... ..	228,066	6 ea.	Cover ... ..	L3784/1	9 ea.
D.E. Bracket c/w Bearing Bush ... ..	250,412		Handle c/w Fixing Washer ... ..	344,227	1 9 ea.
D.E. Bracket Bearing Bush ... ..	L3522/2	9 ea.	Ignition Stem Ass. ... ..	L3972/4	1 3 ea.
Armature ... ..	250,414		Ignition Key ... ..	L4449/3	6 ea.
Pinion and Sleeve Ass. c/w Retaining Spring, Guide and Washer ... ..	250,415		Ignition Contact Plate c/w Contacts	L4370/1	3 0 doz.†
Main Spring ... ..	250,404		Rotor Insul Plate—thin ... ..	L3947/3	1 9 doz.†
Pinion Retaining Spring ... ..	250,095	1 6 doz.†	Rotor Ass. ... ..	344,071	1 0 ea.
Nut or Main Spring Cup (Shaft D.E.)	L1178/4	1 0 ea.	Switch Spring ... ..	L4542/1	3 0 doz.†
<b>DYNAMO—C45N/2 A86/0</b>			Fixing Spring c/w Screw and Nut	344,197	6 ea.
6v. CLOCK ... ..	228,169	4 5 0 ea.	Warning Light ... ..	318,504	3 6 ea.
Field Coils Set ... ..	228,068	7 0 ea.	Rim and Glass Ass. ... ..	LR41/CP	9 ea.
Terminal Block Ass. ... ..	238,122	2 0 ea.	<b>HEADLAMP—R35/A53</b>		
Cover Ass. c/w Screw (Term. Block)	238,121	9 ea.	6v. BLACK ... ..	500,053	1 7 6 ea.
Band Cover Ass. ... ..	227,015	1 0 ea.	Fixing Bolt only ... ..	NC316/6F	3 0 doz.†
D.E. Bracket Ass. less Bearing ... ..	228,171	2 6 ea.	Fixing Screw Nut ... ..	NC316/18	2 0 doz.†
D.E. Ballrace ... ..	189,308	8 3 ea.	Body Bracket (Rim Locking Screw) ...	NC303/49	3 0 doz.†
Oiler—screw-in-type c/w Spring Ball —(C.E. Bracket) ... ..	237,109	6 ea.	Rim Locking Screw ... ..	500,272	6 ea.
Wick and Spring Ass. (screw-in-type Oiler) ... ..	L4034/1	6 ea.	Reflector c/w Bulb Holder and Interior	500,051A	6 6 ea.
Armature ... ..	228,067	1 5 0 ea.	Bulb Holder c/w Interior ... ..	500,054	1 0 ea.
C.E. Bracket Ass. less Brushes and Terminal Block ... ..	228,083	12 6 ea.	Bulb Holder Interior only—DP ... ..	NC867/6	9 ea.
Brush Set ... ..	203,150	3 3 set	Bulb ... ..	66	3 0 ea.
Brush Spring Set ... ..	228,159	6 set	Front Rim Ass. c/w Joint Bead and Fixing Wires less Glass ... ..	LR243	3 6 ea.
Through Fixing Bolt ... ..	228,066	6 ea.	Glass only ... ..	NC316/7A	2 0 ea.
<b>DISTRIBUTOR—DK4A/0 A53</b>			<b>HEADLAMP—L131 BLACK</b> ... ..	505,063	1 2 0 ea.
CLOCK ... ..	404,288	1 17 0 ea.	<b>HEADLAMP—L131EDS.</b>		
Distributor Cover Securing Clip ... ..	M2375/2	3 0 doz.†	6v. BLACK ... ..	505,062	1 19 6 ea.
Lubricator ... ..	400,304	6 ea.	Reflector Ass. c/w Bulb Holder—L131	505,111	6 6 ea.
C.B. Lever Ass. c/w Angle Ass. and Fixing Parts ... ..	400,415	3 6 ea.	Reflector Ass. c/w Bulb Holder, Thrust Plate, Tension Spring, Swivel Ass. and Joint Bead—L131EDS ... ..	501,308	7 6 ea.
Condenser c/w Clip and Fixing Parts	400,308	2 6 ea.	Action Bracket and Location Shell Ass. ... ..	500,163	3 6 ea.
Distributor Arm Ass. ... ..	400,051	1 3 ea.	Dipper Unit c/w Screws and Washers	501,013	8 6 ea.
Distributor Cover c/w Cable Nuts ... ..	400,135	3 6 ea.	Dipper Unit Fuse (box of 6) ... ..	FA8	1 6 box
Distributor Carbon and Spring ... ..	M43	6 ea.	Set of Dipper Swivel Parts ... ..	500,160	9 set
Distributor Cover Cable Nuts ... ..	M3156/4	4 0 doz.†	Bulb Holder Ass.—L131 ... ..	500,061	9 ea.
Securing Plate Ass. ... ..	400,367	1 3 ea.	Set of Bulb Holder Interior Components	500,181	6 set
Driving Dog ... ..	M1106/4	6 ea.	Front Rim Ass. less Glass ... ..	505,620	4 0 ea.
Screwdriver and Gauge Ass. ... ..	400,174	6 ea.	Glass ... ..	MW534	1 6 ea.
Shaft and Action Plate ... ..	400,116	4 6 ea.	Bulb ... ..	106	2 6 ea.
Auto Advance Weight ... ..	400,147	1 3 ea.			

JOSEPH LUCAS LTD.  
PHONE: SERVICE PARTS & REPAIRS—CEN. 8401 †BIRMINGHAM 19, ENGLAND  
TELEGRAMS: "LUCAS, BIRMINGHAM."



# SPARE PARTS & COMPLETE UNITS

DESCRIPTION OF PART.	QUOTE THIS PART NO.	ENGLISH LIST PRICE.
<b>SIDELAMP—LD105</b>		
6v. BLACK ... ..	522,203	£ s. d. 5 3 ea.
Base ... ..	521,204	3 0 doz.†
Fixing Screw Ass. ... ..	520,342	6 ea.
Fixing Screw ... ..	520,325	4 0 doz.†
Fixing Screw Nut ... ..	181,260	2 6 doz.†
Reflector c/w Joint Bead & Fxg. Wires	522,223	1 0 ea.
Bulb Holder c/w Interior Components	520,340	6 ea.
Front Rim Ass. c/w Fixing Wires ...	522,221	9 ea.
Glass only ... ..	521,215	6 ea.
Bulb ... ..	200	1 3 ea.
<b>STOP TAIL LAMP—ST38/AS/L2</b>		
6v. BLACK ... ..	520,428	14 6 ea.
Contact Ass. ... ..	NC446/6A	2 0 ea.
Front Rim Ass. less Glass (black) ...	520,445	1 0 ea.
Glass ... ..	520,410	1 3 ea.
Bulb 6v. ... ..	200	1 3 ea.
<b>TAIL LAMP—T101/6v.</b>		
C/W CABLE BLACK ... ..	521,039	6 0 ea.
Body c/w Ruby and Clear Windows ...	NC447/5	1 9 ea.
Fixing Shell Ass. ... ..	NC447/6	1 6 ea.
Bulb Holder Interior Components ...	ST415	6 set
Bulb ... ..	200	1 3 ea.
<b>HORN C/W BRACKET</b>		
—HF935/2 6v. BLACK ... ..	700,315	1 3 0 ea.
Horn Movement ... ..	700,340	1 3 0 ea.
Bracket Ass. ... ..	700,301	2 0 ea.
Bracket Fixing Screw ... ..	108,278	2 6 doz.†
Bush (Bracket Fixing) ... ..	700,280	2 0 doz.†
Bracket Fixing Nut ... ..	170,020	1 6 doz.†
<b>SCREENWIPER—DW3 A53</b>		
Front Cover Ass. c/w Fixing Parts ...	731,050	1 3 6 ea.
Brushgear Ass. ... ..	730,926	1 9 ea.
Wound Coil and Pole Ass. ... ..	730,790	1 9 ea.
Armature Ass. ... ..	730,937	3 6 ea.
Lubricator and Wick Ass. ... ..	731,017	6 0 ea.
Intermediate Gear and Pinion Ass. ...	730,386	6 ea.
Arm Ass. 5½in. EB ... ..	730,787	1 3 ea.
Squeeze Ass. 8in. E.B. ... ..	732,116	2 6 ea.
...	727,802	2 0 ea.
<b>SCREENWIPER—MT12 A53</b>		
Wound Coil and Pole Ass. ... ..	729,679	1 8 6 ea.
Rotor and Cam Ass. ... ..	L4671/2	3 9 ea.
Intermediate Gear and Pinion Ass. ...	725,472	5 0 ea.
...	725,401	1 6 ea.

DESCRIPTION OF PART.	QUOTE THIS PART NO.	ENGLISH LIST PRICE.
<b>SCREENWIPER—Contd.—</b>		
Oscillating Bush ... ..	L5584/2	£ s. d. 1 6 ea.
Contact Maker Ass. ... ..	725,480	3 0 ea.
Knob ... ..	L3153/2	6 ea.
Arm Ass. 5½in. EB ... ..	732,116	2 6 ea.
Squeeze Ass. 8in. EB ... ..	727,802	2 0 ea.
<b>SCREENWIPER—MT12 A66</b>		
Wound Coil and Pole Ass. ... ..	729,684	1 5 6 ea.
Rotor and Cam Ass. ... ..	L4671/2	3 9 ea.
Lubricator and Wick ... ..	725,472	5 0 ea.
Intermediate Gear and Pinion Ass. ...	730,386	6 ea.
Knob (rotor) ... ..	725,401	1 6 ea.
Contact Breaker Ass. ... ..	L3153/2	6 ea.
Driving Peg ... ..	725,480	3 0 ea.
Squeeze Ass. ... ..	188,865	6 doz.†
Arm Ass. ... ..	727,802	2 0 ea.
Screw (Arm Fixing) ... ..	727,973	2 6 ea.
...	106,281	3 0 doz.†
<b>MIRROR—(Saloon Model)</b>		
... ..	No.28 c/w Bkt.	4 0 ea.
Mirror (2½in. x 4½in. bevelled) ...	NC2102/7	1 9 ea.
Mirror Bracket complete ... ..	N1267	2 6 ea.
Fixing Plate and Ball Stud Ass. ...	580,113	8 ea.
<b>MIRROR—(Tourer Model)</b>		
... ..	No.135 c/w SG Bkt.	5 6 ea.
Mirror Ass. c/w Screw ... ..	580,296	4 0 ea.
SG Bracket (black) ... ..	SG Bkt.	1 6 ea.
Set of Nuts and Washers ... ..	ST695	9 set
<b>TRAFFICATOR—SF34C 6v.</b>		
Trafficator Movement ... ..	538,396	15 6 ea.
Arm c/w Top Cover and Bulb Lead	538,410	15 6 ea.
less Bulb ... ..	531,605	5 0 ea.
Bulb ... ..	255	2 0 ea.
Fixing Plate No. 15C ... ..	538,316	9 ea.
Fixing Plate Screw ... ..	100,033	1 6 doz.†
<b>CONTROL ARM—CS58A/1</b>		
Clip Ass. ... ..	310,239	13 6 ea.
Horn Push and Dipper Switch ... ..	310,207	9 ea.
Trafficator Switch ... ..	380,101	4 3 ea.
...	310,396	2 6 ea.
<b>BATTERY—LESS COVER AND FITTINGS</b>		
Terminal Lug complete—pos. ... ..	SLTW11E/ Dry 2	5 0 ea.
Terminal Lug complete—neg. ... ..	S2267/1/L	2 3 ea.
Vent Plug c/w Washer ... ..	S2267/2	9 ea.
...	S2106/4D	5 6 doz.†

†—Each price 6d. †

**JOSEPH LUCAS LTD.**  
PHONE: SERVICE PARTS & REPAIRS—CEN. 8401

**BIRMINGHAM 19, ENGLAND**  
TELEGRAMS "LUCAS BIRMINGHAM"



In England

BRITISH MADE